

Struck Corporation
W51 N545 Stuck Lane
PO Box 307
Cedarburg, WI 53074

Phone: (262) 377-3300
Email: parts@struckcorp.com
Text: 262-233-4292

Abbreviated parts list for the MAGNATRAC MD567& MD200.

****All prices are subject to change daily.** Thank you.**

Part#	Description	Price
000028	Pulley, 3-1/2" OD x 1" Bore	\$19.50
000047	Handgrip, 5/8" ID	\$1.75
000234kit	Track Rod Kit (Includes: (1) track tension spring.	\$55.27
000236 Replaced by	#000235-up Washer, (1-9/16" OD x 7/16" ID)	\$0.57
000252kit	Bearing kit - (1" ID x 2" OD) Set screw & (2) Shells.	\$16.10
000424 Discontinued	Customer can find the Brake Band on AMAZON. " Rotary 9195 Brake Band" for Go-carts	
000425	Drum, Brake, 4" OD x 1" Bore, Sprocket/Shaft.	\$30.48
000429	Hand throttle control assembly with nut (universal cable).	\$25.30
000430	Choke cable push/pull control	\$13.86
000441	Neutral safety switch	\$15.00
000443	Solenoid, 3 post electrical type (MD750) please contact a local Kohler dealer.	\$57.04
000444	Ignition switch with key, nut, and lock washer.	\$14.03
000445	AMP Meter, Part #AONN1O67A	\$25.56
000716	Steel Washer, (1"ID x 1-1/2" OD).	\$0.78
000933A Replaced by	#004562-Kit Replacement Seat	\$126.47
001029ZZ	Fuel tank assembly - Incudes: 4.5-gallon painted steel tank, #001081 Lockable cap.	\$212.74
001162	Seat Switch, Normally Closed.	\$13.41
001699kit2	Replacement track set if center to center chain measurement is 3-1/2".	\$2,356.80
001925kit3	3.75 Idler pulley with drain hole	\$90.55
001999	1" "E" Snap Ring	\$0.57
002038-up	Pull Assembly, rear axle (requires 2)	\$14.96
002041-up	Power Shaft Welded Assembly	\$289.35
002043	Pulley, "V", 14" OD x 1" bore, 1/4" keyway	\$39.74
002047	Pulley, "V", Idler 4" OD x 3/8" Bore, Main Drive Belt	\$18.15
002048-up	Hardened Sprocket Shaft, unpainted	\$80.08
002049-1	Front Idler Sprocket (assembled, dual chain) - Newer Style(MD200 & MD567)	\$296.83
002049-2	Front Idler Sprocket (assembled, dual chain) – Old Style (MD200 & MD567)	\$296.83
002050-1	Rear Drive Sprocket (assembled, dual chain) – Newer Style (MD200 & MD567)	\$367.28
002050-2	Rear Drive Sprocket (assembled, dual chain) – Old Style (MD200 & MD567)	\$367.28
002051 Replaced by	#001925kit3 3.75 Idler pulley with drain hole.	\$90.55
002052-up	Sleeve, Half, Power Shaft	\$16.80
002053	Nipple, Power Shaft	\$14.60
002056kit	Bearing Kit (includes (2) shells & (1) bearing)	\$31.20
002058	Safety Module Kit (includes (1) plug , (1) safety module)	\$17.19
002060	Grip, handle, red	\$3.96
002061	1/8" NPT straight zerk.	\$0.97
002062	Spring, Main Clutch Handle	\$10.02
002063 Discontinued	No longer Avail. (Grainger would be a good resource)	
002065-up	Axle, Front or Rear - 1 3/16" diameter.	\$92.44
002078	Clutch Belts Forward/Reverse	\$37.57
002079	Power-Rated, Belt, Single Flat V - Belt, Main Drive.	\$74.80

002082A	#50H Chain, 61 pitches without connector link (#001805B)	\$43.40
002082B Replaced by	#001805B 50H Connector link.	\$3.99
002311	Hyd. Pump, D17AA1A	\$288.32
002311B	Hydraulic Filter, BE-10-18 (MD567)	\$17.44
002401	MD567 Heavy Duty Bearing Conversion Kit.	\$183.36
002408	BB73 Main Drive Belt, double "V."	\$133.30
002450 Replaced by	#001699-kit2 Replacement tracks	\$2356.80
002588kit	Set of Tracks for Includes: double lengths of CA557 chain with 3 1/2 center to center distance. (See TO8G Grouser shoes)	\$1909.60
004348kit-4	Rubber Track System WITH CENTER IDLERS – (MD567)	\$3152.89
004562-kit2	Replacement Seat Kit with normally "open" seat switch, (MD567)	\$157.42
004562-kit3	Replacement Seat Kit with normally "closed" seat switch, (MD200)	\$156.02
TO8G	Set of Grouser Shoes fits the 002588Kit	\$607.69
TSO58	Grouser Track Shoe Kit fits the #001699 Replacement track set	\$445.00

Shipping costs will be added to your order amount. We accept Visa, Mastercard, American Express, Discover, Pay Pal and checks with a 2-week waiting period.



